

Fig. 1

RECEIVED
JUN 30 2003
TC 2800 MAIL ROOM



RECEIVED
JUN 30 2003
1C 2800 MAIL ROOM





Fig. 2A



Multichip Ceramic Package 28




R =
measured
resistance
during temperature
ramp-up and ramp-down

RECEIVED
JUN 30 2003
FC 2800 MAIL ROOM

Fig. 2B



Defective Part with Intermittent Short (W1008)




Ohms, Vcc to Ground

RECEIVED
JUN 30 2003
TC 2800 MAIL ROOM

Fig. 3A

Part W1008 After Removal of Short



RECEIVED
JUN 30 2003
TC 2800 MAIL ROOM

Fig. 3B



Defective Epoxy Contact on Part (W1020)




Fig. 4

RECEIVED
JUN 30 2003
TC 2800 MAIL ROOM



RECEIVED
JUN 30 2003
TC 2800 MAIL ROOM

Part W1020 After Repair of Defective Epoxy Contact




Fig. 5




Fig. 6A



RECEIVED

JUN 30 2003

TC 2800 MAIL ROOM




Fig. 6B